

**Federal Aviation  
Administration**

**Transmittal Letter 22-13**

**April 29, 2022**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/16/2022	GA	Atlanta	Hartsfield - Jackson Atlanta Intl	2/4353	4/14/2022	ILS OR LOC RWY 10, ILS RWY 10 (SA CAT I), ILS RWY 10 Amdt 5A

**AIRAC Date: 16 JUNE 2022**

FDC 2/4353 ATL IAP HARTSFIELD - JACKSON ATLANTA INTL, ATLANTA, GA. ILS OR LOC RWY 10, AMDT 5A..., ILS RWY 10 (SA CAT I), AMDT 5A..., ILS RWY 10 (CAT II), AMDT 5A..., ILS RWY 10 (CAT III), AMDT 5A ....  
DELETE NOTE: SIMULTANEOUS APPROACH AUTHORIZED WITH RWY 9L OR 8R OR 8L OR 9L AND 8L.  
CHART NOTE: SIMULTANEOUS APPROACH AUTHORIZED WITH RWY 9L OR 8R OR 8L, OR RWYS 9L AND 8L. PROCEDURE NOT AUTHORIZED WHEN GLIDE SLOPE NOT AVAILABLE (ILS PROCEDURES ONLY).  
THIS IS ILS OR LOC RWY 10, AMDT 5B..., ILS RWY 10 (SA CAT I), AMDT 5B..., ILS RWY 10 (CAT II), AMDT 5B..., ILS RWY 10 (CAT III), AMDT 5B. 2204061810-PERM