

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY  | AIRPORT         | FDC<br>NUMBER | FDC<br>DATE | SUBJECT                       |
|---------------|-------|-------|-----------------|---------------|-------------|-------------------------------|
| 5-Mar-15      | FL    | Tampa | Tampa Executive | 5/2826        | 01/13/15    | ILS OR LOC RWY 23,<br>Amdt 1B |

**AIRAC Date: 5 March 2015**

FDC **5/2826** VDF IAP TAMPA EXECUTIVE, TAMPA, FL. ILS OR LOC RWY 23, AMDT 1B... DELETE NOTE: RWY 23, STRAIGHT-IN AND CIRCLING AND CIRCLING TO RWY 18/36 NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 18,36 NA. THIS IS ILS OR LOC RWY 23, AMDT 1C. 1501121410-PERM