

**Federal Aviation
Administration**

Transmittal Letter 23-25

October 13, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/30/2023	NC	Statesville	Statesville Rgnl	3/5924	9/6/2023	ILS Y OR LOC Y RWY 28, Orig-A

AIRAC Date: 30 NOVEMBER 2023

FDC 3/5924 SVH IAP STATESVILLE RGNL, STATESVILLE, NC. ILS Y OR LOC Y RWY 28, ORIG-A... DELETE
PROFILE NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 50). DELETE NOTE:
DME REQUIRED. DELETE PROFILE NOTE LOC ONLY. DELETE ASTERISK FROM MINIMUM ALTITUDE 1760
AT ICENU I-SVH 3.6 DME. DELETE ASTERISK FROM VDP AT I-SVH 2 DME. PBN REQUIREMENTS NOTE:
DME REQUIRED. THIS IS ILS Y OR LOC Y RWY 28, ORIG-B. 2309051813-PERM