

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 19-01

November 16, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-54
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3-Jan-19	ND	Fargo	Hector Intl	8/6518	11/1/18	ILS OR LOC RWY 18, Orig-C

AIRAC Date: 3 JANUARY 2019

**FDC 8/6518 FAR IAP HECTOR INTL, Fargo, ND. ILS OR LOC RWY 18, ORIG-
C... DELETE NOTE: ASR. CHART CIRCLING ICON. EQUIPMENT
REQUIREMENTS NOTE: ADF OR DME REQUIRED FOR PROCEDURE
ENTRY. DELETE PLANVIEW NOTE: ADF OR DME REQUIRED. THIS IS ILS OR
LOC RWY 18, ORIG-D. 1809101630-PERM**