

**Federal Aviation
Administration**

Transmittal Letter 20-21

August 21, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/8/2020	OH	Harrison	Cincinnati West	0/6923	8/4/2020	Takeoff Minimums and Obstacle DP, Amdt 2

AIRAC Date: 8 OCTOBER 2020

FDC 0/6923 I67 ODP CINCINNATI WEST, HARRISON, OH. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 2... DELETE TAKEOFF MINIMUMS: RWY 9,
27, NA - OBSTACLES. ALL OTHER DATA REMAINS AS PUBLISHED. THIS IS TAKEOFF
MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT 2A. 2007311332-PERM