

**Federal Aviation
Administration**

Transmittal Letter 24-21

August 16, 2024

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/3/2024	TX	Stamford	Arledge Fld	4/0082	5/29/2024	RNAV (GPS) RWY 35, Orig-B

AIRAC Date: 3 OCTOBER 2024

FDC 4/0082 F56 IAP ARLEDGE FLD, STAMFORD, TX. RNAV (GPS) RWY 35, ORIG-B... CHART NOTE:
CIRCLING NA TO RWYS 8/26 AND 13/31. CHANGE PLANVIEW NOTE TO READ: PROCEDURE NA FOR
ARRIVALS AT ROTAN ON V62 NORTHWEST BOUND. THIS IS RNAV (GPS) RWY 35, ORIG-C. 2405291135-
PERM