

**Federal Aviation
Administration**

Transmittal Letter 20-19

July 24, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/10/2020	NC	Lincolnton	Lincolnton- Lincoln County Rgnl	0/2311	7/21/2020	ILS Z OR LOC Z RWY 23, Orig-B

AIRAC Date: 10 SEPTEMBER 2020

FDC 0/2311 IPJ IAP LINCOLNTON-LINCOLN COUNTY RGNL, LINCOLNTON, NC. ILS Z OR
LOC Z RWY 23, ORIG-B... GATEQ FIX MINIMUMS: CIRCLING CAT B MDA 1440/HAA 562.
THIS IS ILS Z OR LOC Z RWY 23, ORIG-C. 2007202133-PERM