

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-14

May 22, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
25-Jun-15	CA	Riverside	Riverside Muni	5/7816	05/08/15	RNAV (GPS) RWY 9, Amdt 2A

EFFECTIVE 25 JUNE 2015

FDC **5/7816** RAL IAP RIVERSIDE MUNI, RIVERSIDE, CA. RNAV (GPS) RWY 9,
AMDt 2A... DELETE NOTE: WHEN VGSI INOP, CIRCLING RWY 34 NA AT
NIGHT.. DELETE NOTE: CIRCLING TO RWY 16 NA AT NIGHT.. THIS IS RNAV
(GPS) RWY 9, AMDT 2B. 1505071301-PERM