

**Federal Aviation
Administration**

Transmittal Letter 22-08

February 18, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3/24/2022	MN	Granite Falls	Granite Falls Muni/Lenzen -Roe-Fagen	2/8604	2/8/2022	VOR/DME RWY 33, Orig-C

AIRAC Date: 24 MARCH 2022

FDC 2/8604 GDB IAP GRANITE FALLS MUNI/LENZEN-ROE-FAGEN MEML FLD, GRANITE FALLS, MN.
VOR/DME RWY 33, ORIG-C... AIRPORT ELEVATION 1048. CIRCLING CAT A MDA 1540/HAA 492, CAT B/C
MDA 1580/HAA 532, CAT D MDA 1700/HAA 652. THIS IS VOR/DME RWY 33, ORIG-D. 2201271522-PERM