

**Federal Aviation
Administration**

Transmittal Letter 23-09

March 3, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
4/20/2023	NY	New York	John F Kennedy Intl	3/8629	1/31/2023	Takeoff Minimums and Obstacle DP, Amdt 9

AIRAC Date: 20 APRIL 2023

FDC 3/8629 JFK ODP JOHN F KENNEDY INTL, NEW YORK, NY. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES AMDT 9... ADD TAKEOFF OBSTACLE NOTE:
RWY 31R, ACFT TAILS 1878 FT FROM DER, 476 FT LEFT OF CENTERLINE, 64 FT AGL/ 74
FT MSL. ALL OTHER DATA REMAINS AS PUBLISHED. THIS IS TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES, AMDT 9A. 2301302047-PERM