

**Federal Aviation
Administration**

Transmittal Letter 18-10

March 23, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMB	FDC DATE	SUBJECT
26-Apr-18	LA	Lafayette	Lafayette Rgnl/Paul Fournet Field	8/1753	3/16/18	ILS OR LOC RWY 22L, Amdt 5C

AIRAC Date: 26 APRIL 2018

FDC **8/1753** LFT IAP LAFAYETTE RGNL/PAUL FOURNET FIELD, Lafayette, LA. ILS OR LOC RWY 22L, AMDT 5C... DELETE NOTE: **RVR 1800 AUTHORIZED WITH THE USE OF FD OR AP OR HUD TO DA. CHART NOTE: **RVR 1800 AUTHORIZED WITH USE OF FD OR AP OR HUD TO DA (NA WHEN USING ACADIANA RGNL ALTIMETER SETTING). CHART PROFILE NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 49.5). THIS IS ILS OR LOC RWY 22L, AMDT 5D. 1803141422-PERM