

**Federal Aviation  
Administration**

**Transmittal Letter 17-18**

**July 14, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Aug-17	NC	Winston Salem	Smith Reynolds	7/2484	7/5/17	RNAV (GPS) RWY 33, Orig-A

**AIRAC Date: 17 AUGUST 2017**

FDC 7/2484 INT IAP SMITH REYNOLDS, Winston Salem, NC. RNAV (GPS) RWY 33, ORIG-A... CHART NOTE: ASTERISK, ASTERISK RVR 1800 AUTHORIZED WITH USE OF FD OR AP OR HUD TO DA. CHANGE LPV DA TO LPV DA ASTERISK, ASTERISK. CHART NOTE: CIRCLING RWY 4, 22 NA AT NIGHT. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT GSO VORTAC ON V103 NORTHBOUND AND V310 EASTBOUND. CHANGE MISSED APPROACH TO READ: CLIMB TO 3500 DIRECT CATSI AND ON 333.00 TRACK TO INGON AND HOLD, CONTINUE CLIMB-IN-HOLD TO 3500. DELETE NOTE: NIGHT LANDING RWYS 15 AND 22 NA. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVAL AT GSO VORTAC VIA V103 NORTHBOUND AND V310 EASTBOUND. THIS IS RNAV (GPS) RWY 33, ORIG-B. 1706291502-PERM