

**Federal Aviation
Administration**

Transmittal Letter 23-22

September 1, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/5/2023	HI	Kahului	Kahului	3/1978	8/17/2023	VOR Z OR TACAN RWY 20, Amdt 1

AIRAC Date: 5 OCTOBER 2023

FDC 3/1978 OGG IAP KAHULUI, KAHULUI, HI. VOR Z OR TACAN RWY 20, AMDT 1...
CHANGE MISSED APPROACH TO READ: CLIMB TO 5000 ON OGG R-188 TO HARPO
INT/OGG 16.71 DME THEN RIGHT TURN ON LNY R-095 TO KEIKI/17.00 DME AND HOLD.
AIRPORT DIAGRAM: REMOVE VYI NDB. THIS IS VOR Z OR TACAN RWY 20, AMDT 1A.
2307251333-PERM