

**Federal Aviation
Administration**

Transmittal Letter 24-02

November 24, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12/28/2023	TX	Lockhart	Lockhart Muni	3/4048	11/2/2023	RNAV (GPS) RWY 18, Orig-B

AIRAC Date: 28 DECEMBER 2023

FDC 3/4048 50R IAP LOCKHART MUNI, LOCKHART, TX. RNAV (GPS) RWY 18, ORIG-B...
DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT SEEDS ON V198-212 AND
V556 EASTBOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT SEEDS
ON T256 EASTBOUND. THIS IS RNAV (GPS) RWY 18, ORIG-C. 2310311301-PERM