

**Federal Aviation
Administration**

Transmittal Letter 13-20

August 16, 2013

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,
Identified as follows:...EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/19/13	MS	Indianola	Indianola Muni	3/9451	8/7/13	VOR/DME A, AMDT 9B

AIRAC Date: 19 SEPTEMBER 2013

FDC **3/9451** IDL FI/P IAP INDIANOLA MUNI, INDIANOLA, MS. VOR/DME A, AMDT 9B... DELETE NOTE: PROCEDURE NA FOR ARRIVALS AT GLH VOR/DME ON AIRWAY RADIALS 010 CW 143. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT SQS VORTAC ON AIRWAY RADIAL 273. THIS IS VOR/DME A, AMDT 9C.