

**Federal Aviation
Administration**

Transmittal Letter 15-22

September 11, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION.....						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
15-Oct-15	MN	Glenwood	Glenwood Muni	5/7838	08/26/15	RNAV (GPS) RWY 33, Amdt 1A

AIRAC Date: 15 October 2015

FDC **5/7838** GHW IAP GLENWOOD MUNI, GLENWOOD, MN. RNAV (GPS) RWY 33, AMDT 1A... DELETE NOTE: STRAIGHT-IN / CIRCLING RWY 33 PROCEDURE NA AT NIGHT.

THIS IS **RNAV (GPS) RWY 33, AMDT 1B**. 1508241813-PERM