U.S. Department of Transportation

Federal Aviation Administration

**Transmittal Letter 23-05** 

**January 6, 2023** 

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVEUPONPUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2/23/2023	KS	Clay Center	Clay Center Muni	2/3239	11/3/2022	RNAV (GPS) RWY 17 Amdt 1

## AIRAC Date: 23 FEBRUARY 2023

FDC 2/3239 CYW IAP CLAY CENTER MUNI, CLAY CENTER, KS. RNAV (GPS) RWY 17, AMDT 1... DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT HURDO ON V553 NORTHEAST BOUND. THIS IS RNAV (GPS) RWY 17, AMDT 1A. 2210311406-PERM