

**Federal Aviation
Administration**

Transmittal Letter 23-11

March 31, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5/18/2023	MO	Columbia	Columbia Rgnl	3/4628	3/15/2023	ILS OR LOC RWY 2, Amdt 18

AIRAC Date: 18 MAY 2023

FDC 3/4628 COU IAP COLUMBIA RGNL, COLUMBIA, MO. ILS OR LOC RWY 2, AMDT 18...
DELETE I-COU LR-209. CHART COU LR-209. THIS IS ILS OR LOC RWY 2, AMDT 18A.
2301181742-PERM