

**Federal Aviation
Administration**

Transmittal Letter 22-17

June 24, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/11/2022	TX	Baytown	Baytown	2/4057	6/17/2022	RNAV (GPS) RWY 32, Orig-A

AIRAC Date: 11 AUGUST 2022

FDC 2/4057 HPY IAP BAYTOWN, BAYTOWN, TX. RNAV (GPS) RWY 32, ORIG-A... LNAV MDA 520/HAT 492
ALL CATS. CIRCLING CAT A MDA 520/HAA 486. CHANGE PBN REQUIREMENTS NOTE TO READ: RNP APCH
- GPS. DELETE NOTE: RADAR REQUIRED. CHART FAS OBST: 214 TOWER (48-158976) 294549N/0945533W.
THIS IS RNAV (GPS) RWY 32, ORIG-B. 2205131817-PERM