

**Federal Aviation
Administration**

Transmittal Letter 21-03

December 11, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1/28/2021	CA	Madera	Madera Muni	0/4637	12/7/2020	RNAV (GPS) RWY 12, Amdt 2

28 JANUARY 2021

FDC 0/4637 MAE IAP MADERA MUNI, MADERA, CA. RNAV (GPS) RWY 12, AMDT 2...
CHART FAS OBST: 319 TREE 365959N/1200648W. DELETE NOTE: CIRCLING NA TO RWYS
8 AND 26. THIS IS RNAV (GPS) RWY 12, AMDT 2A. 2011050901-PERM