

**Federal Aviation
Administration**

Transmittal Letter 21-11

April 2, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5/20/2021	NY	Massena	Massena Intl-Richards Fld	1/3364	3/18/2021	ILS OR LOC RWY 5, Amdt 3B

AIRAC Date: 20 MAY 2021

FDC 1/3364 MSS IAP MASSENA INTL-RICHARDS FLD, MASSENA, NY. ILS OR LOC RWY 5, AMDT 3B... APT ELEV 221. CIRCLING CAT A/B HAA 579, CAT C MDA 880/HAA 659, CAT D HAA 679. CHANGE ALTIMETER NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE POTSDAM ALTIMETER SETTING AND INCREASE DA TO 528 FEET AND ALL VISIBILITIES 1/4 SM; INCREASE ALL MDAS 80 FEET, VISIBILITY CAT C AND D 1/8 SM AND CIRCLING VISIBILITY CAT C AND CAT D 1/4 SM. THIS IS ILS OR LOC RWY 5, AMDT 3C. 2103101312-PERM