

**Federal Aviation
Administration**

Transmittal Letter 20-21

August 21, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/8/2020	TX	Harlingen	Valley Intl	0/6521	8/3/2020	VOR/DME Y OR TACAN RWY 31, Amdt 1A

AIRAC Date: 8 OCTOBER 2020

FDC 0/6521 HRL IAP VALLEY INTL, HARLINGEN, TX. VOR/DME Y OR TACAN RWY 31,
AMD 1A... CHART CIRCLING ICON. ALTERNATE MINIMUMS: CAT A/B 1000-2, CAT C/D
1000-3, NA WHEN LOCAL WEATHER NOT AVAILABLE. THIS IS VOR/DME Y OR TACAN
RWY 31, AMDT 1B. 2007301419-PERM