

**Federal Aviation  
Administration**

**Transmittal Letter 23-08**

**February 17, 2023**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3/23/2023	NJ	Millville	Millville Muni	3/9571	2/6/2023	ILS OR LOC RWY 10, Amdt 2F

**AIRAC Date: 23 MARCH 2023**

FDC 3/9571 MIV IAP MILLVILLE MUNI, MILLVILLE, NJ. ILS OR LOC RWY 10, AMDT 2F...  
DELETE NOTE: CIRCLING TO RWY 32 NA AT NIGHT. DELETE PROFILE NOTE: \* LOC ONLY.  
DELETE ASTERISK FROM 980 MINIMUM ALTITUDE AT XECRE INT. THIS IS ILS OR LOC  
RWY 10, AMDT 2G. 2302011422-PERM