PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|--------|-------------|---------------|-----------|---------------------------------|
| 5/30/13 | MT | Helena | Helena Rgnl | 3/7968 | 1 /1/1/13 | RNAV (GPS) X RWY 27, Amdt 1A |

FDC **3/7968** HLN FI/P IAP HELENA RGNL, HELENA, MT. RNAV (GPS) X RWY 27, AMDT 1A... CHART PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT. CHART NOTE: CIRCLING TO RWY 5, 23, 34 NA AT NIGHT. THIS IS RNAV (GPS) X RWY 27, AMDT 1B.