

**Federal Aviation
Administration**

Transmittal Letter 22-24

September 30, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/3/2022	CO	Montrose	Montrose Rgnl	2/7520	9/19/2022	VOR RWY 13, Amdt 9D

AIRAC Date: 3 NOVEMBER 2022

FDC 2/7520 MTJ IAP MONTROSE RGNL, MONTROSE, CO. VOR RWY 13, AMDT 9D... CHANGE NOTE TO
READ: RWY 13 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART PLANVIEW
NOTE: PROCEDURE NA FOR ARRIVALS AT BRUUK ON V484 SOUTHEAST BOUND. CHART PLANVIEW
NOTE: PROCEDURE NA FOR ARRIVAL ON MTJ VOR/DME AIRWAY RADIALS 297 CW 013. THIS IS VOR RWY
13, AMDT 9E. 2209141937-PERM