

**Federal Aviation
Administration**

Transmittal Letter 17-21

August 25, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
12-Oct-17	NY	Syracuse	Syracuse Hancock Intl	7/4831	8/14/17	RNAV (GPS) Z RWY 28, Amdt 2B

AIRAC Date: 12 OCTOBER 2017

FDC **7/4831** SYR IAP SYRACUSE HANCOCK INTL, Syracuse, NY. RNAV (GPS) Z
RWY 28, AMDT 2B... LPV DA VISIBILITY RVR 1800 ALL CATS. DELETE PLANVIEW
NOTE: PROCEDURE NA FOR ARRIVALS AT WEEPY VIA V145 NORTHWEST
BOUND. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT WEEPY
ON V145 NORTHWEST BOUND. DELETE PLANVIEW NOTE: PROCEDURE NA FOR
ARRIVALS AT TEBOR VIA V433-483 SOUTHEAST BOUND. CHART PLANVIEW
NOTE: PROCEDURE NA FOR ARRIVALS AT TEBOR ON V433-483 SOUTHEAST
BOUND. THIS IS RNAV (GPS) Z RWY 28, AMDT 2C. 1707202226-PERM