U.S. Department of Transportation

800 Independence Ave., S.W. Washington, D.C. 20591

## Federal Aviation Administration

**Transmittal Letter 16-07** 

February 12, 2016

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/ MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: 						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
31-Mar- 16	АК	Allakaket	Allakaket	5/8218	01/27/16	RNAV (GPS) RWY 23, Amdt 1

## EFFECTIVE 31 MARCH 2016

FDC **5/8218** 6A8 IAP ALLAKAKET, ALLAKAKET, AK. RNAV (GPS) RWY 23, AMDT 1... DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA.. CHART NOTE: VISIBILITY REDUCTION BY HELICOPTER BELOW 3/4 SM NA.. CHANGE: THRE 441 TO TDZE 441.. CHART BETTLES ASOS.. THIS IS RNAV (GPS) RWY 23, AMDT 1A. 1511252026-PERM