

**Federal Aviation
Administration**

Transmittal Letter 24-23

September 13, 2024

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/31/2024	AL	Andalusia	South Alabama Rgnl At Bill Benton	4/7059	7/29/2024	NDB-A, Amdt 4

AIRAC Date: 31 OCTOBER 2024

FDC 4/7059 79J IAP SOUTH ALABAMA RGNL AT BILL BENTON FLD, ANDALUSIA, AL. NDB-A, AMDT 4...
CHANGE ALTERNATE MINIMUMS TO READ: NA. CHANGE ALTIMETER SETTING NOTE TO READ: WHEN
LOCAL ALTIMETER SETTING NOT RECEIVED, USE OZR ALTIMETER SETTING AND INCREASE ALL MDAS
100 FEET AND VISIBILITY CAT C/D 1/2 SM. THIS IS NDB-A, AMDT 4A. 2407031421-PERM