

**Federal Aviation
Administration**

Transmittal Letter 23-17

June 23, 2023

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/10/2023	MI	West Branch	West Branch Community	3/7051	5/18/2023	RNAV (GPS) RWY 9, Orig-B

AIRAC Date: 10 AUGUST 2023

FDC 3/7051 Y31 IAP WEST BRANCH COMMUNITY, WEST BRANCH, MI. RNAV (GPS) RWY 9, ORIG-B... LNAV MDA 1660/HAT 778 ALL CATS. TDZE 882. CHANGE NOTE TO READ: RWY 9 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. DELETE NOTE: NIGHT LANDING: RWY 9 NA. CHART NOTE: STRAIGHT-IN RWY 9 NA AT NIGHT, CIRCLING RWY 9 NA AT NIGHT. CHANGE PLANVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVALS AT LADIN ON V133 NORTHWEST BOUND AND T265 SOUTHWEST BOUND. THIS IS RNAV (GPS) RWY 9, ORIG-C. 2305161543-PERM