

**Federal Aviation  
Administration**

**Transmittal Letter 20-23**

**September 18, 2020**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/5/2020	ME	Dexter	Dexter Rgnl	0/0280	9/11/2020	RNAV (GPS) RWY 16, Orig-A

**AIRAC Date: 5 NOVEMBER 2020**

FDC 0/0280 1B0 IAP DEXTER RGNL, DEXTER, ME. RNAV (GPS) RWY 16, ORIG-A...  
DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT ANSYN ON V104  
WESTBOUND. THIS IS RNAV (GPS) RWY 16, ORIG-B. 2009101745-PERM