

**Federal Aviation  
Administration**

**Transmittal Letter 21-19**

**July 23, 2021**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

| By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:<br>.....EFFECTIVE UPON PUBLICATION |       |                    |              |            |          |                              |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--------------------|--------------|------------|----------|------------------------------|
| AIRAC<br>DATE                                                                                                                                                                                                                                                                                                      | STATE | CITY               | AIRPORT      | FDC NUMBER | FDC DATE | SUBJECT                      |
| 9/9/2021                                                                                                                                                                                                                                                                                                           | TN    | Columbia/<br>Mount | Maury County | 1/9892     | 6/9/2021 | RNAV (GPS) RWY<br>24, Orig-A |

**AIRAC Date: 9 SEPTEMBER 2021**

FDC 1/9892 MRC IAP MAURY COUNTY, COLUMBIA/MOUNT PLEASANT, TN. RNAV (GPS) RWY 24, ORIG-A... CIRCLING CAT B MDA 1360/HAA 679, CAT D MDA 1620/HAA 939. CIRCLING VISIBILITY CAT D 3. CHANGE NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE NASHVILLE INTL ALTIMETER SETTING AND INCREASE LPV DA TO 1090 FEET AND LNAV/VNAV DA TO 1438 FEET AND INCREASE ALL MDA 120 FEET; INCREASE LPV AND LNAV/VNAV ALL CATS VISIBILITY 1/2 SM, AND LNAV CATS C AND D VISIBILITY 1/4 SM, AND INCREASE CIRCLING CAT C VISIBILITY 1/2 SM. ALTERNATE MINIMUMS: CAT A, B, C 800-2 1/4, CAT D 1000-3, NA WHEN LOCAL WEATHER NOT AVAILABLE. THIS IS RNAV (GPS) RWY 24, ORIG-B. 2105041340-PERM