

**Federal Aviation
Administration**

Transmittal Letter 21-15

MAY 28, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/15/2021	VA	Warrenton	Warrenton- Fauquier	1/9559	4/16/2021	LOC/DME RWY 15, Orig-A

Airac Date: 15 JULY 2021

FDC 1/9559 HWY IAP WARRENTON-FAUQUIER, WARRENTON, VA. LOC/DME RWY 15, ORIG-A... CIRCLING CAT C MDA 880/HAA 544, CAT D MDA 980/HAA 644. CHANGE NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE CULPEPER ALTIMETER SETTING AND INCREASE ALL MDAS 40 FEET AND CIRCLING CAT D VISIBILITY 1/4 SM. THIS IS LOC/DME RWY 15, ORIG-B. 2104141729-PERM