

LNDRE FOUR DEPARTURE (RNAV)



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAYS 13L/R: Climb heading 133° to 1000, thence. . . .

. . . . direct to cross DRSET at or above 4000, then on track 133° to cross HAYZZ at or above 6000, then on track 132° to cross SHRAM at or above 7000, then on track 088° to LNDRE, then on (transition). Maintain 8000.
Expect filed altitude 10 minutes after departure.

TAKEOFF RUNWAYS 31L/R: Climb heading 313° to 2700, thence. . . .

. . . . right turn heading 013° or as assigned by ATC, maintain 3000, expect RADAR vectors to cross SHRAM at or above 7000, then on track 088° to LNDRE, then on (transition).
Expect filed altitude 10 minutes after departure.

BDDAY TRANSITION (LNDRE4.BDDAY)

BSKAT TRANSITION (LNDRE4.BSKAT)

FORCK TRANSITION (LNDRE4.FORCK)

LOOSE TRANSITION (LNDRE4.LOOSE)

MRSSH TRANSITION (LNDRE4.MRSSH)

ZALEA TRANSITION (LNDRE4.ZALEA)

SC-2, 03 JAN 2019 to 31 JAN 2019

SC-2, 03 JAN 2019 to 31 JAN 2019