

DALLAS FOUR DEPARTURE

FORT WORTH, TEXAS



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 16R: Climb heading 166° to 1100 before turning right.

When entering controlled airspace, fly assigned heading and altitude, expect vector to appropriate route.

BELCHER TRANSITION (DALL4.EIC): From over TTT VOR/DME on TTT R-094 to POTEN, then on EIC R-259 to EIC VORTAC.

EL DORADO TRANSITION (DALL4.ELD): From over TTT VOR/DME on TTT R-084 to SOLDO, then on UIM R-261 to UIM VOR/DME, then on UIM R-072 and ELD R-254 to ELD VOR/DME.

LITTLE ROCK TRANSITION (DALL4.LIT): From over TTT VOR/DME on TTT R-064 to ORTRO, then on LIT R-235 to LIT VORTAC.

MERIDIAN TRANSITION (DALL4.MEI): From over TTT VOR/DME on TTT R-084 to SOLDO, then on UIM R-261 to UIM VOR/DME, then on UIM R-072 and ELD R-254 to ELD VOR/DME, then on ELD R-097 and MEI R-281 to MEI VORTAC.

QUITMAN TRANSITION (DALL4.UIM): From over TTT VOR/DME on TTT R-084 to SOLDO, then on UIM R-261 to UIM VOR/DME.

SAWMILL TRANSITION (DALL4.SWB): From over TTT VOR/DME on TTT R-094 to POTEN, then on EIC R-259 to TEKBE, then on SWB R-291 to SWB VOR/DME.

SIDON TRANSITION (DALL4.SQS): From over TTT VOR/DME on TTT R-084 to SOLDO, then on UIM R-261 to UIM VOR/DME, then on UIM R-072 and ELD R-254 to ELD VOR/DME, then on ELD R-077 and SQS R-262 to SQS VORTAC.

SOLDO TRANSITION (DALL4.SOLDO): From over TTT VOR/DME on TTT R-084 to SOLDO.

TEXARKANA TRANSITION (DALL4.TXK): From over TTT VOR/DME on TTT R-074 to SHERO, then on TXK R-244 to TXK VORTAC.

NOTE: BELCHER TRANSITION: For aircraft inbound to the JAN, MLU and SHV terminal areas only

NOTE: EL DORADO TRANSITION: For aircraft inbound to the Memphis Terminal area.

Aircraft should file and/or expect the appropriate STAR.

NOTE: MERIDIAN TRANSITION: For aircraft inbound to the Atlanta Terminal area.

NOTE: QUITMAN TRANSITION: For aircraft inbound to Shreveport Terminal area.

NOTE: SOLDO TRANSITION: ATC assigned.

SC-2, 03 JAN 2019 to 31 JAN 2019

SC-2, 03 JAN 2019 to 31 JAN 2019