

RADAR REQUIRED for Rwy 6 dept when R-5001 is active. If RADAR inoperative, expect 15 min delay for deactivation of R-5001.

...track and climb as depicted. Maintain 6000 or higher as assigned.

NE-2, 17 APR 2025 to 15 MAY 2025

MC GUIRE FLD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI)