

ILS RWY 28C (SA CAT I)
CHICAGO O'HARE INTL (ORD)

MISSED APPROACH: Climb to 1100 then climbing left turn to 4000 on heading 215° and DPA VOR/DME R-082 to DPA VOR/DME and hold.




113.0 DBK
Chan 77

SEIKA INT
I-VZE [7]
RADAR

HAZIL
I-VZE [12.7]
RADAR

(IF)
RZUKO
I-VZE [15.8]
RADAR

MEMAW
I-VZE [19]
RADAR

KOENN
I-VZE [22.1]
RADAR

SNTOE
I-VZE [25.3]
RADAR

INDUH
I-VZE [28.4]
RADAR

(IAF)
VOGTL

2300
(5.7)

4000
(3.1)

5000
(3.1)

6000
(3.1)

7000
(3.1)

8000
(3.1)

9000
277° (17.2)

093°

2325 A

LOCALIZER 108.95
I-VZE [---]
Chan 26 (Y)

108.4 DPA
R-082
Chan 21

MSA ORD 25 NM
[3400]

MISSED APCH FIX

DUPAGE
DPA [---]
108.4
Chan 21

R-248-068°
248°

ELEV	680	D	TDZE	651
------	-----	---	------	-----

1100 ↑	4000 hdg 215°	DPA R-082	DPA ☐	VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 80).									
SEIKA INT I-VZE 7 RADAR HAZIL I-VZE 12.7 RADAR MEMAW I-VZE 19 RADAR RZUKO I-VZE 15.8 RADAR KOENN I-VZE 22.1 RADAR SNTOE I-VZE 25.3 RADAR LNDUH I-VZE 28.4 RADAR IM 2300 4000 5000 6000 7000 8000 9000 27° GS 3.00° TCH 55 1044' 5 NM 5.7 NM 3.1 NM 3.1 NM 3.1 NM 3.1 NM 3.1 NM													
CATEGORY	A		B		C		D						
S-ILS 28C	RA 155/14		150		DA 801								

SA CATEGORY | ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED