

ILS or LOC RWY 12
SANTA MARIA PUB/CAPT G ALLAN HANCOCK FLD (SMX)

MISSED APPROACH:
Climb to 800, then
climbing left turn to
5000 direct MQO
VORTAC and hold.

MISSED APCH FIX

MORRO BAY
MQO $\equiv \equiv \equiv$
112.4
Chan 71

R-319 139°
319°

(IF/IAF)
WINCH INT
I-SMX 15.4

HILDA OM
I-SMX 6.5

GUADALUPE
113.05 GLJ $\equiv \equiv \equiv$

LOCALIZER 108.9
I-SMX $\equiv \equiv \equiv$
Chan 26

ORCUT
MQO 30

ELEV 261 TDZE 230

120°

SANTA MARIA, CALIFORNIA
Amdt 10B 24FEB22

SANTA MARIA PUB/CAPT G ALLAN HANCOCK FLD (SMX)
34°54'N-120°27'W

ILS or LOC RWY 12