

VORTAC GLD

115.1

Chan 98

APP CRS

332°

Rwy Idg

5499

TDZE

3654

Apt Elev

3657

VOR RWY 30

RENNER FLD/GOODLAND MUNI (GLD)

⚠

Inoperative table does not apply to S-30 Cat C/D. Circling NA south of Rwy 5 and 30. When local altimeter setting not received, use Burlington, CO altimeter setting and increase all MDA 160 feet; increase S-30 Cat C/D visibilities to 2 miles, Circling Cat C visibility to 2 miles and Circling Cat D visibility to 2 ¼ miles. Circling Rwy 5, 23 NA at night. Circling NA to Rwys 17 and 35.

MALSR

MISSED APPROACH: Climbing right turn to 5600 in GLD VORTAC holding pattern.

ASOS 121.025	DENVER CENTER 132.7 226.675	UNICOM 122.8 (CTAF) 0
-----------------	--------------------------------	--------------------------

ELEV 3657

TDZE 3654

5600 GLD	GLD VORTAC	Remain within 10 NM		
152°	332°	5600		
CATEGORY	A	B	C	D
S-30	4200-1½ 546 (600-1½)		4200-1⅝ 546 (600-1⅝)	
CIRCLING	4200-1 543 (600-1)		4200-1⅝ 543 (600-1⅝)	4240-2 583 (600-2)

GOODLAND, KANSAS

Amclt 9C 30JAN20

39°22'N-101°42'W

RENNER FLD/GOODLAND MUNI (GLD)

VOR RWY 30

NC-2, 17 APR 2025 to 15 MAY 2025

NC-2, 17 APR 2025 to 15 MAY 2025