

NDB RWY 25

NDB/DME UTO 272 Chan 22 (Y)	APCH CRS 256°	Rwy Idg TDZE 1161 Arpt Elev 1261	[USAF]	INDIAN MOUNTAIN LRRS (PAIM)
-----------------------------------	------------------	--	--------	-----------------------------

Night operations not authorized.	MISSED APPROACH: Climb to 5000, then climbing left turn to 6600 direct UTO NDB and hold. Continue climb climb-in-hold to 6600.
----------------------------------	--

ANCHORAGE CENTER APP/DEP CON 124.6 352.0	RCO (FAIRBANKS) 122.6	CTAF 126.2	AWOS-3
---	--------------------------	---------------	--------

CAUTION: Rwy located on a slope of a 3415' mountain with W end at the base of cliff, APPROACH ONLY FROM THE EAST.

Successful go around improbable if initiated past MAP.

Uncontrolled Airspace below 700' AGL within 4 NM of Indian Mountain airport.

Visibility reduction by helicopters NA.

PAPI Beyond 8° right of RCL unusable.

NOT FOR CIVIL USE

MILITARY CERTIFIED
AIRCREWS or AUTHORIZED
CONTRACT AIRCRAFT ONLY

EMERG SAFE ALT 100 NM 10,100

5000 ↑	6600 ↘	UTO 	NDB/DME	ELEV 1261	TDZE 1161
				Land Rwy 25 Takeoff Rwy 7	
CATEGORY				REIL Rwy 25	
S-25				REIL Rwy 25	
CIRCLING				REIL Rwy 25	