


TACAN RWY 32

TACAN BKF Chan 33	APCH CRS 328°	Rwy Idg 11,006 TDZE 5663 Arpt Elev 5663	AL-538 [USAF]	BUCKLEY SFB (KBKF)	
▼ *When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile, CAT CDE vis to 1½ miles. ** Circling NA east of Rwy 14-32.			ALSF-1 	MISSED APPROACH: Climbing right turn to 8200 and intercept BKF TACAN R-148 direct BEKEE and hold or as directed by ATC.	
ATIS ★ 119.675 259.3		DENVER APP CON 128.45 251.075		TOWER ★ 121.0 291.675	
			GND CON 121.6 275.8		CLNC DEL 121.6 275.8

Missed approach requires use of RNAV or ATC RADAR monitoring.



EMERG SAFE ALT 100 NM 16,500

