

|                                        |                        |                                                     |
|----------------------------------------|------------------------|-----------------------------------------------------|
| WAAS<br>CH <b>45635</b><br><b>W33A</b> | APP CRS<br><b>330°</b> | Rwy Idg<br>TDZE <b>7926</b><br>Apt Elev <b>7950</b> |
|----------------------------------------|------------------------|-----------------------------------------------------|

RNAV (GPS) RWY 33

CENTRAL COLORADO RGNL (A.E.J)

⚠

NA

⚠

-22°C

Circling NA northeast of Rwy 15-33. DME/DME RNP-0.3 NA.  
When local altimeter setting not received, use Salida altimeter setting  
and increase all MDA 100 feet. VDP NA with Salida altimeter setting.  
#Missed approach requires minimum climb of 425 feet per NM to 14100.

MISSED APPROACH: Climbing right  
turn to 16000 direct KANON and hold,  
continue climb-in-hold to 16000.

|                          |                                       |                                 |
|--------------------------|---------------------------------------|---------------------------------|
| AWOS-3<br><b>132.925</b> | DENVER CENTER<br><b>119.85 363.15</b> | UNICOM<br><b>122.8 (CTAF) 0</b> |
|--------------------------|---------------------------------------|---------------------------------|

Topographic map showing the RNAV (GPS) RWY 33 approach. The map includes terrain contours, elevation points, and the flight path. Key features include the MSA ROBYV 25 NM, KANON fix, and various altitude and distance markers along the approach path. The map also shows the missed approach procedure and the circling area for RWY 33.

Diagram of the missed approach procedure for RWY 33. It shows a climb from 16000 feet to 18000 feet, then a turn to 330 degrees and a climb to 19000 feet. The diagram also shows the circling area for RWY 33, with a radius of 1.3 NM and a height of 8003 x 75 feet.

| 16000       | KANON            | VGSI and descent angles not coincident<br>(VGSI Angle 3.00/TCH 41). | BUBYO                   |    |
|-------------|------------------|---------------------------------------------------------------------|-------------------------|----|
|             |                  |                                                                     |                         |    |
| *LNAV only. | *1.8 NM to ROBYV | AKNAC                                                               | 12600                   |    |
| ROBYV       | 330°             | 10300                                                               | 338°                    |    |
| 1.3         | 1.8 NM           | 3.4 NM                                                              | 7.7 NM                  |    |
| TCH 41      | 3.44°            |                                                                     |                         |    |
| CATEGORY    | A                | B                                                                   | C                       | D  |
| #LP         | MDA 8960-1½      | 1034 (1100-1½)                                                      | 8960-3<br>1034 (1100-3) | NA |
| LP          | MDA 9840-1½      | 1914 (1900-1½)                                                      | 9840-3<br>1914 (1900-3) | NA |
| #LNAV       | MDA 9300-1½      | 1374 (1400-1½)                                                      | 9300-3<br>1374 (1400-3) | NA |
| LNAV        | MDA 9980-1½      | 2054 (2100-1½)                                                      | 9980-3<br>2054 (2100-3) | NA |
| CIRCLING    | 9980-1½          | 2030 (2100-1½)                                                      | 9980-3<br>2030 (2100-3) | NA |

BUENA VISTA, COLORADO

Orig-B 31MAR16

38°49'N-106°07'W

CENTRAL COLORADO RGNL (A.E.J)

RNAV (GPS) RWY 33