

ILS RWY 28L (SA CAT I & II)
JOHN GLENN COLUMBUS INTL (CMH)

MALS

MA
A5

3

ALTERNATE MISSED
APCH FIX

APPLETON
APE :--
116.7
Chan 114

LOCALIZER 111.75
I-CMH :--
Chan 54(Y)

LOM
BOUTN
230 BU :--

Procedure NA for arrival on APE VORTAC
airway radials 143 CW 264.

BKEYE
I-CMH [9.5]
RADAR

LMJTD
I-CMH [6.3]
RADAR

HAMON
I-CMH [15.2]
RADAR


VUZLI
I-CMH [11.7]
APE [10.8]
RADAR

MSA APE 25 NM
[3100]


ELEV 815 D TDZE 815

D

TDZE 815



1400	3000	BU
		



CATEGORY	A	B	C	D
S-ILS 28L	SA CAT I	RA 157/14	150 DA	965
S-ILS 28L	SA CAT II	RA 100/12	100 DA	915

SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

40°00'N-82°54'W

JOHN GLENN COLUMBUS INTL (CMH)
ILS RWY 28L (SA CAT I & II)