

ILS or LOC RWY 10R
JOHN GLENN COLUMBUS INTL (CMH)

MALSR

MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 direct BU LOM and hold.

ALTERNATE MISSED APCH FIX

055° 235° R-055°

APPLETON
APE ::--
116.7
Chan 114

(IF/IAF)
JOGMA
I-AQI [7.6]
APE [24.2] RADAR
3300 101° (2.1)

AVUSE
I-AQI [9.7] RADAR

SHUUU
I-AQI [4.4] RADAR
1400 1002 I-AQI [2.4] RADAR

DEBBY
I-AQI [2.4] RADAR

LOCALIZER 111.75
I-AQI ::--
Chan 54(Y)

LOM BOUTN
230 BU ::--

ELEV 815 D TDZE 809

Procedure NA for arrival on APE VORTAC airway radials 194 CW 315.

MSA APE 25 NM
[3100]

ELEV 815

D

TDZE 809

TDZ/CL Rwy 10R-28L

HIRL Rwys 10R-28L and 10L-28R

FAF to MAP 4.5 NM					
Knots	60	90	120	150	180
Min:Sec	4:30	3:00	2:15	1:48	1:30

EC-2, 12 JUN 2025 to 10 JUL 2025

EC-2, 12 JUN 2025 to 10 JUL 2025