

TACAN Y RWY 23

TACAN NRB
Chan 51

APCH CRS
221°

Rwy ldg
TDZE
Arpt Elev
8001
15
15

[USN] MAYPORT NS (ADM DAVID L. MC DONALD FLD) (KNRB)

▼ Visibility reduction by helicopters not authorized.

MISSED APPROACH: Climbing left turn to 2000
via NRB TACAN R-081 to HELES and hold.

ATIS ★
236.775

JACKSONVILLE APP CON
124.9 308.4

TOWER ★
118.75 239.30

GND CON
126.5 233.7

ASR/PAR

CRG feeder route requires turn in hold.

CAUTION: Procedure not authorized at night when the VGSI is inop, unless the station has an approved observer watching for marine traffic in the St. John's River channel.

200

CRAIG
114.5 CRG
Chan 92

352
Λ

1074
Λ

2000
072°
(16.2)

254
Λ

320
Λ

MAYPORT
Chan 51 NRB

CAUTION: Vessels with masts up to 150'
transiting the St. Johns River inside
of NRB 2 DME.

MSA NRB 2.5 NM
173°
2200
1500
359°

EMERG SAFE ALT 100 NM 2800

2000
NRB
R-081

HELES
NRB
10

NRB TACAN

LEBAF
NRB
1

JERBI
NRB
4

IKECA
NRB
8

MUKOE
NRB
10

1100

1700

1700

3.01°
TCH 48

3 NM

CATEGORY	A	B	C	D
S-23	520-1 505 (600-1)	520-1½ 505 (600-1½)		
CIRCLING	560-1 545 (600-1)	560-1½ 545 (600-1½)	620-2 605 (700-2)	

ELEV 15

TDZE 15

REIL Rwy 5-23
HIRL Rwy 5-23

MAYPORT, FLORIDA

30°23'N-81°25'W MAYPORT NS (ADM DAVID L. MC DONALD FLD) (KNRB)

Amtd 6 05SEP24

SE-3, 12 JUN 2025 to 10 JUL 2025

SE-3, 12 JUN 2025 to 10 JUL 2025

TACAN Y RWY 23