

APP CRS
328°

Rwy Idg	5256
TDZE	933
Apt Elev	942

RNAV (GPS) RWY 33
GARNER FLD (UVA)

GARNER FLD (UVA)



When local altimeter setting not received, use South Texas Rgnl at Hondo altimeter setting and increase all MDA 100 feet; increase LNAV Cat C/D and Circling Cat C/D visibility ¼ SM. DME/DME RNP-0.3 NA.


MISSED APPROACH:
Climbing right turn to 3500
direct BUXQU WP and hold.

AWOS-3
124.175

HOUSTON CENTER
134.95 269.4


UNICOM
122.8 (CTAF) **L**

RADAR REQUIRED



ELEV 942

TDZE 933




UVALDE, TEXAS
Orig-B 22APR21

3500	BUXQU
------	-------

VGSI and descent angle not coincident
(VGSI Angle 3.00/TCH 35).

4 NM
Holding Pattern



CATEGORY	A	B	C	D
GLS DA	NA			
INAV/ VNAV DA	NA			
INAV MDA	1380-1 447 (500-1)		1380-1¼ 447 (500-1¼)	1380-1½ 447 (500-1½)
CIRCLING	1380-1 438 (500-1)	1460-1 518 (600-1)	1620-2 678 (700-2)	1620-2¼ 678 (700-2¼)

UVALDE, TEXAS
Orig-B 22APR21

GARNER FLD (UVA)

29°13'N-99°45'W

RNAV (GPS) RWY 33