

VORTAC RQZ

112.2

Chan 59

APP CRS

043°

Rwy Idg
TDZE

N/A

Apt Elev

N/A

764

VOR-B

HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)

DME required.

▼

▲

MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold.

AWOS-3PT 120.0	HUNTSVILLE APP CON★ 125.6 354.1	GCO 121.725	UNICOM 123.0 (CTAF) 0
-------------------	------------------------------------	----------------	--------------------------

