

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAYS 16, 17: Climb on heading 164° to 1600 before proceeding on course or as assigned by ATC, thence. . .

TAKEOFF RUNWAYS 34, 35: Climb on heading 344° or as assigned by ATC, thence. . .

. . . expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR3.EAKER) MC ALESTER TRANSITION (NANDR3.MLC) OKMULGEE TRANSITION (NANDR3.OKM) **ROLLS TRANSITION (NANDR3.ROLLS)** TULSA TRANSITION (NANDR3.TUL) WILL ROGERS TRANSITION (NANDR3.IRW) ZEMMA TRANSITION (NANDR3.ZEMMA)