

25219

ILS or LOC RWY 16
BELLINGHAM INTL (BLI)

MISSED APPROACH: Climb to 700 then climbing right turn to 3000 on heading 275° and on YVR VOR/DME R-135 to TECUV/YVR 15.3 DME and hold.

T Autopilot coupled approach NA below 500. For inop ALS, increase S-LOC Cat C/D visibility to RVR 6000.
A *RVR 1800 authorized with use of FD or AP or HUD to DA (NA when using FHR altimeter setting).

ELEV	171	D	TDZE	163
FAF to MAP 5.6 NM				
Knots	60	90	120	150
Min:Sec	5:36	3:44	2:48	1:52

BELLINGHAM INTL (BLI)
ILS or LOC RWY 16