

TAMPA, FLORIDA

ILS or LOC RWY 5

LOC I-MCF
109.5

APCH CRS
044°

Rwy Idg **11,421**
TDZE **10**
Arpt Elev **14**

AL-418 [USAF]

MACDILL AFB (KMCF)

RADAR or DME required.

*When ALS inop, increase RVR to 40, vis to ¾ mile.

**When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE RVR to 60, vis to 1½ miles.

ALS-F-1

MISSED APPROACH: Climb to 2700 via MCF TACAN R-075 to MCF 22 DME and hold. Cross 8 DME at 1700. RNAV or ATC RADAR required for missed approach.

ATIS
133.825 270.1

TAMPA APP CON
124.95 354.0

TOWER
120.175 294.7

GND CON
118.575 275.8

***Circling not authorized NW of Rwy 5-23.

CAUTION:
LOC course offset 2.86° from the extended rwy centerline and intersects the rwy centerline 1834' after the DA.

WARNING: Use extreme caution PETER O. KNIGHT airport 4 NM Northeast of MACDILL AFB.

MACDILL
Chan 47 MCF

LOCALIZER 109.5
I-MCF
LOC offset 2.86°

EMASE
MCF 6.6
RADAR

(IF/IAF)
MILNE
MCF 15

Expect RADAR vectors around St. Petersburg
landmass for noise abatement, unless
otherwise requested by pilot.

MSA MCF 2.5 NM
2700

EMERG SAFE ALT 100 NM 3000

MCF 19

MILNE
MCF 15

EMASE
MCF 6.6
RADAR

1700
MCF R-075

2700
MCF

1600

224°

044°

GS 3.00°
TCH 55

1600

044°

1600

MCF 2.9

EMISE
MCF 2.3

4.3 NM

0.5

TWR
97

offset
LOC
0.43

11.421 x 151

102

044°

161

HIRL Rwy 5-23

FAF to MAP 4.3 NM

Knots

60

90

120

150

180

Min:Sec

4:18

2:52

2:09

1:43

1:26

CATEGORY	A	B	C	D	E
S-ILS 5 *	260/24		250	(300-½)	
S-LOC 5 **	420/24	410 (500-½)	420/40	410	(500-¾)
*** CIRCLING	500-1 486 (500-1)	540-1 526 (600-1)	540-1½ 526 (600-1½)	580-2 566 (600-2)	1020-3 1006(1100-3)

TAMPA, FLORIDA

Amtd 1 18MAY23

27°51'N-82°31'W

MACDILL AFB (KMCF)

ILS or LOC RWY 5

SE-3, 04 SEP 2025 to 02 OCT 2025

SE-3, 04 SEP 2025 to 02 OCT 2025