

TACAN RWY 5

TACAN MCF
Chan 47

APCH CRS
043°

Rwy Idg 11,421
TDZE 10
Arpt Elev 14

AL-418 [USAF]

MACDILL AFB (KMCF)

* When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE RVR to 60, vis to 1½ miles.
** Circling not authorized NW of Rwy 5-23.

ALSF-1
A1

† MISSED APPROACH: Climb to 2700 via MCF R-075 to 22 DME and hold. Cross 8 DME at 1700.

ATIS
133.825 270.1

TAMPA APP CON
124.95 354.0

TOWER
120.175 294.7

GND CON
118.575 275.8

WARNING: Use extreme caution PETER O. KNIGHT arpt 4 NM NE of MACDILL AFB.

MACDILL
Chan 47 MCF

ADNIL MCF
6.4
RADAR

(IF/IAF) MILNE MCF
15

EMERG SAFE ALT 100 NM 3000

Expect RADAR vectors around St. Petersburg landmass for noise abatement, unless otherwise requested by pilot.

† RNAV or ATC RADAR required for missed approach.

MSA MCF 2.5 NM
2700

1700 MCF R-075
2700 MCF 22

FOROM
2.9
2.2

TACAN

TWR 97

161

043°

CATEGORY

A

B

C

D

E

S-5 *

420/24 410 (500-½)

420/40 410 (500-¾)

CIRCLING **

500-1 486 (500-1)

540-1 526 (600-1)

540-1½ 526 (600-1½)

580-2 566 (600-2)

1020-3 1006 (1100-3)

HIRL Rwy 5-23

TAMPA, FLORIDA

27°51'N-82°31'W

MACDILL AFB (KMCF)

Amtd 2 10AUG23

TACAN RWY 5

SE-3, 04 SEP 2025 to 02 OCT 2025

SE-3, 04 SEP 2025 to 02 OCT 2025